



## Roro Automobiles Inc.

374 Boulevard Curé-Labelle  
Laval  
H7V 2S3

# 450-681-5001

### Make / Model

BMW 6 Series B6 ALPINA xDrive ...

Year

Mileage indicated / actual\*

2015

93,019 km

Transmission

Drive Type

automatic

AWD

Engine

Fuel Type

8 cyl. / 4.4 liters

unleaded

Serial number

Stock number

FA618



### EQUIPMENTS

Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Memory seats, Power locks, Power Mirrors, Power driver seat, Power steering, Power windows, Reverse park assist, Steering wheel controls, Adjustable steering wheel, Dual zone A/C, ABS Brakes, Driver airbag, Fog lights, Passenger airbag, Rear defrost, Alarm system, Lateral airbags, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, HID / xenon headlights, AM/FM stereo, CD player, MP3 Player, Navigation system, CD not included, Bucket seats, Displacement L/C1 : 4.4 / 268, Variable speed intermittent wipers, Power tilt / sliding sunroof, Climate control, Electrochromic rearview mirror, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Passenger illuminated vanity mirror, Mirror memory, Pass-Through rear seat, Leather seats, Power passenger seat, Tire pressure monitoring system, Sun / moon roof, Panoramic roof, Rear head air bag, Lateral head airbags, Front floor

### SALE PRICE

# \$54,888

Plus tax.

### Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

### Category

Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:

As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:

A ☐ 6 months or 10 000 km B ☐ 3 months or 5 000 km C ☐ 1 month or 1 700 km

D ☐ Good working (subject to 37, 38 L.P.C.) E ☐ No warranty

### Repairs done and mechanical verification certificate

The following repairs have been done on this vehicle since the dealer's possession.

If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.

### Comments

### Optional repairs

The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Date : \_\_\_\_\_ Signature : \_\_\_\_\_

autoExpert.ca

Sticker # : 6323948